



DXZ4*

BSM Firmware Release Notes – 2.1.0

FW-DXZ4-0010_2_1_0-GA

Last update: 25th April 2018

Revision: 1.0

Contents

Overview	3
Summary	3
Status	3
Resources.....	3
Change Notes	3

Copyright ©2018 Amulet Hotkey Ltd. All rights reserved.

Information in this document is subject to change. No part of this document may be reproduced through any means including (but not limited to) electronic or mechanical, without express written permission from Amulet Hotkey Ltd. Amulet Hotkey Ltd may have patents, patent applications, trademarks or copyrights or other intellectual property rights covering subject matter in this document. “Amulet Hotkey” and “solutions you can bank on” are registered trademarks of Amulet Hotkey Ltd. Other product names and company names listed within this document may be trademarks of their respective owners.

Overview

These release notes are for the Amulet Hotkey DXZ4 (all variants) Board Support Micro (BSM). They provide a summary of key feature additions, enhancements and resolved issues associated with this firmware release.

Issue	Author	Issue date	Details
1.0	AJS	25 Apr 2018	First release

Summary

Firmware	FW-DXZ4-0010_2_1_0-GA
Release Version	2.1.0
Release Date	25/04/2018
SCN	240
Applicable models	All variant of DXZ4*

Status

Urgent	
Recommended	
Optional	✓

Resources

Firmware Download	DXZ4 Firmware - 2.1.0
Documentation	DXZ4 Manual DXZ4 Quick Start Guide

If any issues are experienced during or after an update, please contact [Amulet Hotkey support](#).

Change Notes

- [DXZIV-235] – New feature - Implemented generic SFP support.**
 Previous releases of firmware have only supported those SFP modules defined on the SFP Datasheet ([here](#)). This new version adds support for any standard SFP module.
- [DXZIV-241] – Issue resolution - Flickering NW LINK LED.**
 Non-critical issue of Network Link LED flickering when using the *Memorydealers GLC-FE-100FX-MD* SFP has been resolved.