

Teradici zero client firmware 4.8.2 – Security notice

September 2016

Last updated: 26/09/2018

Issues

The following security issues have been resolved in Teradici zero client firmware version 4.8.2.

Zero client reboot issue: (#53154)

Criticality:	Update recommended
Description:	Teradici zero client firmware 4.8.2 contains a security update that resolves an issue whereby the zero client may reboot when an impaired network condition caused substantial imaging packet loss.
Affected products:	All Amulet Hotkey zero client variants
Affected firmware:	All 4.x firmware versions older than 4.8.2.
Solution:	Update all zero clients to firmware version 4.8.2
Solution impact:	None

Change history

Date	Change
26 th September 2018	Notice published

The information provided in this notice is believed to be accurate and reliable as of the date provided. However, Amulet Hotkey Ltd does not give any representations or warranties, expressed or implied as to the accuracy or completeness of such information. Amulet Hotkey shall have no liability of the consequences or use of such information for any infringement of other rights from third parties that may result from its use. Amulet Hotkey reserves the right to make corrections modifications and other changes to this notice at any time. Customers should obtain the latest relevant information before placing orders and should verify that such information is current and complete. If you have questions about this notice, please contact Amulet Hotkey. Amulet Hotkey | London, +44 (0) 20 7960 2400 | New York, +1 212-269-9300 www.amulethotkey.com | sales@amulethotkey.com